

65\_30\_00.0188\_USU98\_MONT\_US




Fig. 1




Fig. 3-12




Fig. 4, 5, 6 = 7




Fig. 4




Fig. 5




Fig. 6




Fig. 7




Fig. 8




Fig. 9




Fig. 10




Fig. 11




Fig. 12




Fig. 14-23




Fig. 14




Fig. 15




Fig. 16




Fig. 17




Fig. 18




Fig. 19




Fig. 20




Fig. 21




Fig. 22